

STN 115 / 07

DIAMOND VALLEY RAILWAY INC.

STN 115 / 07

Distribution: Stations, Signal Boxes,
Loco Depot, G42.

Office of Signal &
Telegraph Sup't.
Diamond Valley.
Phone Auto 242.
BMC : bc.

4th September, 2007.

SIGNALLING & INTERLOCKING ALTERATIONS

Commencing forthwith, the following interlocking alterations will be effective :-

DIAMOND VALLEY "B":

1. A new No.72 Double ended Points (forming part of a scissors crossover on the Inner & Outer Circle lines in advance of Signal Post No.s 43 & 44) was commissioned and brought into service.
2. A new black lever switch (No.72) was provided on the block shelf in Diamond Valley "B" Signal Box to control the new points. "Normal", "Reverse", "Point Free" and "Out of Correspondence" LED Indications are provided above the lever switch.
3. Signal Post No.43 was altered to show "Medium Speed" aspects for moves from the Down Inner Circle Line to the Down Outer Circle Line. (Note: This signal also shows medium speed aspects for moves towards the Up Through Line.) The "Normal Speed" aspect only applies for moves to the Down Inner Circle Line.

SPECIAL NOTES :

Signallers are asked to monitor the operation of new No.72 points and forward any relevant comments onto the Signal & Telegraph Sup't, for further evaluation.

Train Crews are asked to note the relevant signalling changes, monitor field operation and forward relevant comments onto the Signal & Telegraph Sup't, for further evaluation.

ALL CONCERNED TO NOTE AND ARRANGE ACCORDINGLY.

Bruce. N. McCurry,
Signal & Telegraph Sup't.