

STN 135 / 06

DIAMOND VALLEY RAILWAY INC.

STN 135 / 06

Distribution: Stations, Signal Boxes,
Loco Depot, G42.

Office of Signal &
Telegraph Sup't.
Diamond Valley.
Phone Auto 242.
BMC:bc

31st July, 2006.

DIAMOND VALLEY - MEADMORE JUNCTION (VIA P.T.L)

SIGNALS RESTORED BACK INTO SERVICE

Commencing from 1315 hours, Sunday, 30th July, 2006 following the relocation of conduits and cables due to the construction of the new Nillumbik Carriage Storage Complex, the following will become effective :

1. **Signal Post No.s D45, DV45, UT 45, DV197 & DV225** were restored back into service and the black crosses were removed from the signal hoods.
2. The temporary speed restriction of 5 kph imposed between Signal Post No.s D45 & D71 on the Inner Circle Line, Signal Post No.s DV45 & DV71 on the Outer Circle Line and Signal Post No.s DV 197 & DV257 on the Up Pinetree Loop Line (as advised in Circular STN 130 / 06) **has been lifted** and normal speeds will now apply.
3. The Special Instructions contained in Circular STN 130 / 06 **are hereby cancelled.**

ALL CONCERNED TO NOTE AND ARRANGE ACCORDINGLY.

Bruce. N. McCurry,
Signal & Telegraph Sup't,

Per: BMC